

# PERFORMA FOR THE SAFETY OF SCHOOL BUILDING

## PART-1

(To be filled by the head of School/Institution)

1. (a) Name of the School Building STS WORLD SCHOOL  
(b) Level/Standard of School 10+2  
(c) Weather School is affiliated to CBSE or PSEB If affiliated then affiliation No. CBSE  
1630781
2. Location. VILL RAJ GOMAL P.O. RUKMA KALAN (JAL)
3. Plot Area. 4 ACRE 7 KANAL 98215 (sqft)
4. Plinth Area. \_\_\_\_\_
5. Number of Story. TWO
6. Year of Construction of the building. 2010
7. If the building has been constructed under the supervision of the qualified engineer, the following details may be given:-
  - a) Name the Engineer with Qualification. RAJINDER SINGH (ARCHITECT)
  - b) Address of the Engineer CHAHAL NAGAR (PHAGWARA)
  - c) Detail of structural drawing used in construction. — DO —
  - d) Name & address of architect with qualification. — DO —
8. Whether the building has been constructed for the purpose.
  - a) School - yes
  - b) Residential purpose and converted for use of school. -
9. Material used for the roofs:-
  - a) R.C.C slab. yes
  - b) R.S joints & battens. -
  - c) Wooden joints & battens. -
10. Material used for walls:-
  - a) Mud Motor -
  - b) Cement Motor. yes
  - c) Plaster i) Lime Motor. yes  
ii) Cement Motor. yes
11. Flooring:-
  - a) Conglomerate. \_\_\_\_\_
  - b) Terrazzo. \_\_\_\_\_
  - c) Brick Paving. - yes
12. A detailed drawing indicating dimensions of the rooms along with the size and location of doors and window - yes
13. Weather fire safety certificate obtained from concerned fire officer. - yes
14. It is also certified that there is no any court case or stay is pending regarding this building in any hon'ble court - yes.

5

*Princip*

Principal  
S.T.S World School  
Vill. Rajgomal P.O. Rurka Kalan  
Distt. Jalandhar

PART-II

**SCHOOL BUILDING SAFETY CERTIFICATE**

**(TO BE FILLED BY THE S.D.E OF P.W.D. B & R DEPARTMENT)**

Name of School STS World School Vill. Rajgomed  
P.O. Rurka Kalan Teh. Phillur Distt. Jalandhar

1) This office Assistant Engineer/Junior Engineer visited the above mentioned School on 03/04/2023 and have visually inspected it for its safety and find it fit for normal use as a school building

2) In case any addition or expansion and modification to this building is to be carried out same may be done under the supervision of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.

3) In case the building is effected by flood, or if there is settlement of walls/foundation or sagging of roofs etc immediately inspection of the undersigned be arranged to check the stability and the safety of the building.

4) This building is found visually safe hence it is expected that it can be safely occupied for normal use up to (indicate year upto which it can be used)

(2023-24) (31-3-2024) Under normal condition only.

Ref. No. 39

Dated: 17/04/2023

Fi  
Sub Divisional Engineer  
Provl. Sub Division  
PWD B & R Nakodar

17/4/23  
Executive Engineer  
Construction Division No. 1,  
PWD B & R, Jalandhar Cantt